



W-3499K Check Valve Kit Eaton/Char-Lynn H Series Motors

- 1) Thread (2) W-3500 elbows into 7/8" - 14SAE O-Ring motor ports.
- 2) Thread W-3476 fitting and W-3499 check valve into elbows (use a light coat of thread sealing compound).
As shown on drawing below.
- 3) Thread W-3501 tube to pipe adapters into fitting (use a light coat of thread sealing compound) and check valve.
- 4) Slide fitting nut and tapered split ring over each end of W-3490 tube. Insert each end of tube into fittings. Push tube in until it clears O-ring in each fitting. Fasten nuts and tapered split rings to fittings. Turn nuts hand tight, then tighten one turn or until rear of tapered split ring is flush with nut. **DO NOT OVERTIGHTEN.**

